0037 Norman H. Bangerter

State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

of por

Governor

Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340

INSPECTION REPORT

| Permittee and/or Operator's Name: Co-Op Mining Company Business Address: Post Office Box 300, Huntington, Utah 84528 Mine Name: Bear Canyon Permit Number: ACT/015/025 Type of Mining Activity: Underground X Surface Other County: Emery State: Utah Company Official(s): Beth Owen, Wendell Owen, and Gerald Hansen State Officials(s): Hugh Klein and Henry Sauer (DOGM) Federal Official(s): N/A Partial: X Complete Date of last Inspection: 1 & 2 July 1991 Weather Conditions: Clear and cool Acreage: Permitted1060 Disturbed16 Regraded Seeded Bonded Enforcement Action: None | | | | |
|---|---|-------------------|--------------------------|--|
| COMPLIANCE WITH PERMITS AND PERFORM | MANCE | OIAM | PHKU | 2 |
| 1. PERMITS 2. SIGNS AND MARKERS 3. TOPSOIL 4. HYDROLOGIC BALANCE: | YES (x) (x) | <u>NO</u> () () | N/A () () () | COMMENTS (x) (x) (x) |
| a. STREAM CHANNEL DIVERSIONS b. DIVERSIONS c. SEDIMENT PONDS AND IMPOUNDMENTS d. OTHER SEDIMENT CONTROL MEASURES e. SURFACE AND GROUNDWATER MONITORING f. EFFLUENT LIMITATIONS 5. EXPLOSIVES 6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL 7. COAL PROCESSING WASTE 8. NONCOAL WASTE 9. PROTECTION OF FISH, WILDLIFE AND | (_) (_) (x) (_) (_) (_) (_) | | | (_) (x) (x) (_) (_) (_) |
| RELATED ENVIRONMENTAL VALUES 10. SLIDES AND OTHER DAMAGE 11. CONTEMPORANEOUS RECLAMATION 12. BACKFILLING AND GRADING 13. REVEGETATION 14. SUBSIDENCE CONTROL 15. CESSATION OF OPERATIONS 16. ROADS a. CONSTRUCTION | (x) () () () () () | | | (x) () () () () () |
| b. DRAINAGE CONTROLS c. SURFACING d. MAINTENANCE 17. OTHER TRANSPORTATION FACILITIES 18. SUPPORT FACILITIES | (x) () | | | (x) () |

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>3</u>

PERMIT NUMBER: ACT/015/025 DATE OF INSPECTION: 2 August 1991

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

1 & 2)

Signage and paperwork were checked to confirm the address of Co-Op Mining's main office and resident agent. This was also done as part of the standard AVS checks.

4c)

Sediment pond A was found to be in good condition with a minor amount of standing water. Pond B was satisfactory, however, erosion was noted at the base of the inlet that comes off the haul road. Gerald Hansen was made aware of the need to rip-rap and grout this area (the inlet above this point has previously been rip-rapped and grouted).

4d)

Periodic discharges flow into Bear Creek at UPDES discharge point 004. These discharges vary in frequency and duration. In addition, the velocity and flow also vary. Due to some of the high velocities that occur and the orientation of the line, there is some concern as to the long-term stability of the right bank of the creek within 5 to 10 feet of where the discharge impacts. Gerald Hansen was made aware of this concern and the need to provide some type of armoring for the bank.

9)

Canadian thistle (as identified by Henry Sauer) was noted near the lump coal pile. Mr. Sauer pointed out that this is considered a noxious weed, and that according to Emery County, the landowner is responsible for weed control. This was also pointed out to Wendell Owen and Gerald Hansen. Mr. Hansen informed the above inspectors that the weeds had been sprayed recently.

16b)

Drainage ditches below pond B and above the gate were clean and in working order. One portion of the ditch on the north side of the road was noted as having a leaky water line below it. The location of this and the need for immediate repair was pointed out to Mr. Hansen.

(Continuation sheet)

Page <u>3</u> of <u>3</u>

Copy of this Report:

Mailed to: Brian Smith (OSM)

Wendell Owen (Co-Op)

Given to: Joe Helfrich (DOGM

Pam Grubaugh-Littig (DOGM)

Inspector's Signature & Number: Hugh Gt NO Date: Date: